


- Surge Inundation Limit - FEMA assessment of extent of high water, based on after storm measurements and topology
- Army Corps of Engineers (ACoE) Blue Tarp Assessment - aerial imagery derived residential building assessment with minor roof damage, assessment based on HAZUS-MH Technical Manual roof damage classification. This is equivalent to roof cover loss greater than 2% but no more than 15%.
- FEMA September 9, 2005 Damage Estimate -
- Limited - Generally superficial damage to solid structures (e.g., loss of tiles or roof shingles); some mobile homes and light structures are damaged or displaced.
- Moderate - Solid structures sustain exterior damage (e.g., missing roofs or roof segments); some mobile homes and light structures are destroyed, many are damaged or displaced.
- Extensive - Some solid structures are destroyed; most sustain exterior and interior damage (e.g., roofs missing); most mobile homes and light structures are destroyed.
- Catastrophic - Most solid and all light or mobile structures destroyed.

- 18 foot elevation contour
- 20 foot elevation contour
- 22 foot elevation contour



Gulfport, Mississippi - The Impact of Hurricane Katrina
 NOAA Aerial Imagery Acquired August 30, 2005

20080607
 Crowsey Incorporated
 Stanardsville - Virginia - 22973
 434.985.9171 - www.crowsey.com
 rick@crowsey.com